

Industrial Bolting Safety Guide

General preparation checklist for torque and tensioning work. Project procedures and manufacturer instructions always take precedence.

Before work	Confirm joint procedure, tool rating, reaction point and PPE
Tool setup	Inspect sockets, hoses, couplers, power supply and calibration status
Operation	Keep clear of reaction and pinch zones; increase load in controlled stages
After work	Release stored pressure, inspect equipment and record completion data